

Power Inverter Diode Installation

November 21, 2016 Page **1** of **3**

1877652-7465

Fax: 250 952-0275

AMBULANCE TYPE: D

Demers Chevrolet Ambulances

UNITS AFFECTED:

63300-63349, 63360-63369, 63400-63457

ISSUE: GM Recall "42230 Shortened Powered Accessory Availability" reprograms the vehicle's PCM and BCM for the alternator to produce more voltage. This higher voltage causes the ambulance power inverter to produce an "Over Voltage" trouble code, causing the power inverter to stop working.

ACTION: Install a diode in the Power Inverter switch/sensor circuit.

LABOUR TIME: Bill to BC Ambulance .2 HRS


LABOUR CODE: CMOID

Use the above labour code on the invoice to identify this procedure has been completed.

SERVICE PROCDURE:

Follow the picture instructions below. Be sure to read the complete instructions before performing the modification.

Identify if the inverter you are working on is an option A or B.



Follow the corresponding instructions below for the affected option.



Power Inverter Diode Installation


November 21, 2016 Page **2** of **3**

AMBULANCE TYPE:

Demers Chevrolet Ambulances

UNITS AFFECTED:


63300-63349, 63360-63369, 63400-63457



Use a screwdriver to remove wire.



Remove wire.



Crimp and heat shrink diode assembly.



Reinstall wire in connector.

1 877 652-7465

Fax: 250 952-0275



Power Inverter Diode Installation

November 21, 2016 Page **3** of **3**


AMBULANCE TYPE:

Demers Chevrolet Ambulances

UNITS AFFECTED:

63300-63349, 63360-63369, 63400-63457





Locate switching wire entering inverter.
Cut switching wire and insulate inverter end.
Re-route harness wire to opposite end of inverter.



Crimp and heat shrink diode assembly.



Install wire in connector. See below schematic.

1 877 652-7465

Fax: 250 952-0275

