



**British Columbia  
Ambulance Service**  
Emergency and Health Services Commission

# Memorandum

**Fleet Operations**  
PO Box 9615 Stn Prov Govt  
3300 Douglas St  
Victoria BC V8W 9P1

date

CLIFF:

File:

To: Affected Unit Chiefs  
Affected Service Centers

## **Re: Oxygen Bottle Retaining Collar Upgrade**

BCAS has main oxygen bottles in use that have different machined collars on the tank top. Fleet request the following procedure to be performed to all Demers built vehicles 63... to 63... that have not previously been modified in order to provide proper restraint of oxygen tanks.

### **Procedure:**

Remove existing tank mounting bracket and replace with supplied bracket with new mounting hardware.



Modification kits have been sent to affected service centers.

Please contact Demers for payment.

For any questions or concerns please call Fleet Operations at **1-877-652-7465**.

*Please read complete modification procedure before proceeding with repair:*

**British Columbia Ambulance Service**

Professionalism - Accountability - Responsiveness - Teamwork - Wellness

