

 BC Ambulance Service BC Emergency Health Services		October 2, 2017 Page 1 of 1
AMBULANCE TYPE:	Ford V10 Gas Engine Ambulances	
UNITS AFFECTED:	Crestline Re-mounted Ambulances	

ISSUE: Ford V10 gas engine oil consumption.

ACTION: Service intervals changed to 6,000 km or 4 months.

SERVICE PROCEDURE:

LABOUR TIME: 0.1 hrs.

At the next scheduled A service, replace the service record decal located on the headliner of each affected ambulance with the corresponding supplied decal.

Check the vehicle service history to make sure the new service record decal is correctly up to date.

