



BC Ambulance Service
BC Emergency Health Services

175-15 Rear Door Garbage BIN MODIFICATION

February 22, 2016
Page 1 of 1

AMBULANCE TYPE: DEMERS MX151D-BCAS

UNITS AFFECTED: 62800 - 62999

ISSUE: Rear door wire garbage bag holders are failing in service.


ACTION: Replace existing wire bag holder with removable hard shell bin & support shelf

SERVICE PROCEDURE:

1. Remove old hardware
2. Drill 1/8" holes at locations shown
3. Mount shelf & pad eyes with screws provided
4. Install bin and retaining strap

Kit includes:

Shelf, Bin, strap, 2 pad eyes,
7 - #8 self-tapping screws



Please code this modification on your invoice as: **GMOGB** Labour Time: **.5 Hour**

Any questions or concerns please contact Fleet @ 1 877 652 7465